

Locksley Woods COA

Report #: 32686-1 Greenville, NC # of Units: 178

Level of Service: Update "With-Site-Visit" January 1, 2023 through December 31, 2023

Findings & Recommendations

| as of January | 1. | 2023 |
|---------------|----|------|
|---------------|----|------|

| Project Starting Reserve Balance | \$286,832 |
|---------------------------------------------------|-------------|
| Currently Fully Funding Reserve Balance | \$2,460,984 |
| Average Reserve Deficit (Surplus) Per Unit | \$12,214 |
| Percent Funded | |
| Recommended 2023 Fully Funding Contributions | \$115,700 |
| Recommended 2023 Special Assessments for Reserves | \$534,000 |
| Recommended 2024 Special Assessments for Reserves | |
| Most Recent Reserve Contribution Rate | • |

Reserve Fund Strength: 11.7% Weak Fair Strong < 30% < 70% > 130% **Risk of Special Assessment:** High Medium Low

Economic Assumptions:

| Net Annual "After Tax" Interest Earnings Accruing to Reserves | |
|---------------------------------------------------------------|--|
| Annual Inflation Rate | |

This report is an "Update, With-Site-Visit" Reserve Study based on a prior study prepared by Association Reserves for your 2018 Fiscal Year. We performed the site inspection on 8/23/2022

This Reserve Study was prepared or overseen by a credentialed Reserve Specialist (RS). As of the start of the initial fiscal year shown in this study, your Reserve fund is determined to be 11.7 % Funded. Based on this figure, the Client's risk of special assessments & deferred maintenance is currently High. The objective of your multi-year Funding Plan is to Fully Fund your Reserves, where clients enjoy low risk of such Reserve cash flow problems.

Based on this starting point, your anticipated future expenses, and your historical Reserve contribution rate, our recommendation is to increase your Reserve contributions to \$115,700 in the upcoming fiscal year. Going forward, the contribution rate recommended here should be increased as illustrated on the 30-yr Summary Table. It is also recommended that two special assessments occurs in 2023 and 2024 to the amount of \$534,000 each year. This is to prepare the reserve account for the inevitable reserve component project costs. Especially the roofs and drainage projects.



| # | Component | Useful Life (yrs) | Rem. Useful Life (yrs) | Current Average Cost |
|------|-------------------------------------|----------------------|------------------------------|----------------------------|
| | Site and Grounds | | | |
| 2107 | Concrete Sidewalks - Repair | 5 | 2 | \$7,650 |
| 2113 | Site Drainage System - Clean/Repair | 30 | 1 | \$60,000 |
| 2123 | Asphalt - Seal/Repair | 5 | 7 | \$25,600 |
| 2125 | Asphalt Phase 1 - Resurface | 25 | 3 | \$157,850 |
| 2125 | Asphalt Phase 2 - Resurface | 25 | 4 | \$157,850 |
| 2139 | Site Fencing (Wood) - Replace | 30 | 0 | \$2,500 |
| 2158 | Retaining Walls - Repair | 30 | 0 | \$13,000 |
| 2160 | Retention Ponds - Maintain | 30 | 12 | \$76,500 |
| 2166 | Mailboxes - Replace | 25 | 2 | \$21,050 |
| 2169 | Entry Sign - Refurbish | 35 | 18 | \$19,500 |
| 2183 | Trees - Trim/Remove | 2 | 0 | \$7,450 |
| 2185 | Landscaping - Refurbish | 25 | 4 | \$65,000 |
| 2541 | Trash Dumpster - Replace | 20 | 17 | \$13,750 |
| 2543 | Security Cameras - Upgrade/Replace | 10 | 6 | \$3,600 |
| 2560 | Fire Extinguishers - Replace | 10 | 8 | \$5,750 |
| 2591 | Irrigation System - Repair | 20 | 1 | \$46,500 |
| 2803 | BBQs - Replace | 20 | 6 | \$11,500 |
| 3043 | Water Table Repair - Allowance | 5 | 4 | \$13,550 |
| | Pool Area | | | |
| 2367 | Pool House Doors - Replace | 40 | 8 | \$10,250 |
| 2501 | Entry System - Replace | 12 | 8 | \$3,400 |
| 2750 | Bathrooms - Refurbish | 30 | 2 | \$5,105 |
| 2763 | Pool Deck Furniture - Replace | 10 | 5 | \$5,345 |
| 2769 | Pool Deck - Resurface (15%) | 25 | 2 | \$10,800 |
| 2771 | Pool Fence - Replace | 35 | 7 | \$15,700 |
| | Pool - Resurface | 12 | 4 | \$28,650 |
| | Pool Filters - Replace | 20 | 6 | \$4,650 |
| | Pool Pumps - Replace | 10 | 2 | \$4,000 |
| | Pool Cover - Replace | 15 | 5 | \$7,600 |
| | Building Exteriors | | | |
| 2303 | Ext. Lights (Decorative) - Replace | 25 | 0 | \$17,150 |
| | Balcony Railings - Replace | 30 | 7 | \$82,500 |
| | Walkway Deck Railings - Replace | 30 | 7 | \$122,500 |
| | Staircases/Handrails - Maintain | 20 | 2 | \$66,500 |
| | Vinyl Siding (Phase 1) - Replace | 40 | 17 | \$577,500 |
| | Vinyl Siding (Phase 2) - Replace | 40 | 18 | \$577,500 |
| | Roof Phase 1 (Comp Shingle)-Replace | 25 | 2 | \$512,500 |
| | lation Reserves #32686-1 | | _ | 9/26/2022 |

| # Component | Useful Life (yrs) | Rem. Useful Life (yrs) | Current Average Cost |
|------------------------------------------|----------------------|------------------------------|----------------------------|
| 2381 Roof Phase 2 (Comp Shingle)-Replace | 25 | 3 | \$512,500 |
| 2387 Gutters/Dspts - Replace | 30 | 3 | \$39,750 |
| 3030 Bldg Exterior - Refurb | 5 | 3 | \$7,500 |

38 Total Funded Components

Note 1: Yellow highlighted line items are expected to require attention in this initial year, light blue highlighted items are expected to occur within the first-five years.